


# I-70 Extended Life Pavement Performance

Charles Wienrank, P.E.  
Pavement Design Engineer  
IDOT - Bureau of Research


# I-70 Project Location




**District 7 Clark County  
(Constructed by District 5)**



# I-70 Clark County



# Average Daily Truck Traffic



# Why Use Extended Life Pavement Design?

- Warranty demonstration project mandated by Illinois FIRST legislation in 1999
  - "The Department shall implement a demonstration project, under which 20 of the contracts ... for fiscal years 2000 through 2004 shall have a performance-based warranty of at least 5 years..."
- Also required extended life designs
  - "10 of those contracts shall be designed for a 30-year life cycle."
- Asphalt industry wished to compete on "30-year life cycle" warranty projects

# What Is An Extended Life HMA Design?

- Built to last longer than the standard 20-year design
- Will not require major rehabilitation or patching
- Surface is sacrificial and is replaced at some frequency

# I-70 Project Details

- IL 1 to Indiana Border – Contract 70044
  - Unbonded CRCP Overlay (2002)
- Martinsville to IL 1 – Contract 70059
  - HMA / Rubblized CRCP (2003)
- 5-year warranties on both projects (pavement and bridges)
- 20-year warranties were considered (at IAPA's request)


# I-70 Project Details (cont.)

- Alternate bidding was considered
- Zero blanking band used for surface testing of pavement
- Bridge decks constructed 1/4 inch high and diamond ground for smoothness

# Unbonded CRCP Overlay – Design Details

- Existing 8-in. CRCP (1969) with D-cracking susceptible aggregates and 2 prior asphalt overlays
- 30-year (extended life) design period
- 12.0-in. unbonded CRCP overlay of existing (after mill to profile)

# UBOL Construction Sequence




# HMA / Rubblized CRCP – Design Details


- Existing 8-in. CRCP (1971) with D-cracking susceptible aggregates and 2 prior asphalt overlays
- 30-year (extended life) design period
- 17.5-in. HMA on rubblized CRCP
- 5.25-in. overlay of existing CRCP (control)

# Design Curve Used in 2001


HMA Overlay Thickness  
for Rubblized Pavements



# Limiting Strain Criterion (Maximum) Thickness – 11.50 inches



# Rubb. Construction Sequence



# Extended Life HMA Elements

- Steel slag SMA surface
- Polymer used in all lifts
- 1.0% hydrated lime (dry) anti-strip in all lifts
- Polymer tack coat between lifts
- Extra tack coat on longitudinal joints
- Material transfer device on all lifts
- Did not use rich bottom base layer

# **Rubblization and HMA Construction**

# Multi-Head Breaker



# Broken Pavement Behind Multi-Head Breaker



# Z-Grid Roller



# Rubblized Pavement Ready for HMA Overlay



# HMA Lifts

<b>Lift Thickness (in)</b>	<b>Mix Information</b>	<b>Binder Grade</b>
<b>2.00</b>	<b>N80 SMA 12.5 Surface Course</b>	<b>SBS PG 76-28</b>
<b>2.50</b>	<b>N105 19.0 Binder Course</b>	<b>SBS PG 76-28</b>
<b>3.00</b>	<b>N105 19.0 Binder Course</b>	<b>SBS PG 76-28</b>
<b>10.00 (2 lifts)</b>	<b>N90 19.0 Binder Course</b>	<b>SBS PG 70-22</b>

# I-70 HMA Core



# I-70 HMA Core




# Open House




# Project Monitoring

- Traffic
- Data collection vehicles
  - Digital imagery
  - International Roughness Index (IRI)
  - Rutting
- Distress surveys
- Falling weight deflectometer testing

# Percent Consumed



# Traffic Trends 1950-2017



# Condition Rating Survey (CRS)

- CRS 9.0 – 7.6 = Excellent
- CRS 7.5 – 6.1 = Good
- CRS 6.0 – 4.6 = Fair
- CRS 4.5 – 1.0 = Poor

# Unbonded CRCP Overlay – Performance

- 2018 CRS=7.7, IRI=75
- Centerline deterioration (low level)
- **Edge punchouts** (around 3 per mile) with (temporary) spray injection patching
- Permanent patching (very little)
- Some warranty repairs

# 2018 DCV Image



# Edge Punchout



# HMA / Rubblized CRCP – Performance

- 2018 CRS=8.0, IRI=48
- Rutting=0.11 in.
- Centerline deterioration is only recorded CRS distress
- No warranty repairs on pavement (some bridge deck repairs)

# 2018 DCV Image




# Mechanical Damage



# Car Fire Damage



# Down Image (3D)




# Mill and Overlay




# Reflective D-Cracking




# CRS vs Age




# IRI vs Age




# 2018 IRI by 0.1-mile (HMA)



# 2018 IRI by 0.1-mile (CRCP)



# Rutting vs Age





# Warranted Distresses (5-yr.)

<b>Parameter</b>	<b>Extent</b>	<b>Severity</b>	<b>Warranty Work</b>
<b>Fatigue Cracking</b>	<b>50 sq. ft.</b>	<b>Moderate</b>	<b>Patch 150% of Distressed Area</b>
	<b>Any within section</b>	<b>High</b>	
<b>Block Cracking</b>	<b>100 sq. ft.</b>	<b>Moderate</b>	<b>Mill &amp; Replace</b>
	<b>Any within section</b>	<b>High</b>	
<b>Transverse Cracking</b>	<b>10 lin. ft.</b>	<b>Moderate</b>	<b>Seal</b>
	<b>Any within section</b>	<b>High</b>	

# Warranted Distresses (5-yr.)

## *Longitudinal Cracking*

Location	Extent	Severity	Warranty Work
Within the Lane	10 lin. ft.	Moderate	Seal
	Any within section	High	
Centerline Deterioration	10 lin. ft.	High	
Edgeline	10 lin. ft.	High	

# Warranted Distresses (5-yr.)

<b>Parameter</b>	<b>Extent</b>	<b>Severity</b>	<b>Warranty Work</b>
<b>IRI</b>	<b>Within Section</b>	<b>Avg. 110 in./mi.</b>	<b>Mill &amp; Replace</b>
<b>Potholes &amp; Shoving</b>	<b>Any within section</b>	<b>All severity levels</b>	<b>Patch 150% of Distressed Area</b>
<b>Bleeding, Flushing, &amp; Raveling</b>	<b>500 sq. ft.</b>	<b>Moderate</b>	<b>Mill &amp; Replace</b>
	<b>Any within section</b>	<b>High</b>	
<b>Rut Depth</b>	<b>Any within section</b>	<b>0.30 in.</b>	<b>Mill &amp; Replace</b>

# Performance Summary

- Overall performance has been excellent on both projects
- CRCP UBOL has experienced edge punchouts that have required maintenance
- SMA surface has been maintenance free for 15+ years with minimal rutting

# Performance Summary (cont.)

- IRI values on HMA/Rubb. have been consistently lower than those on CRCP UBOL
- Rubblized section performed much better than the mill and overlay control section

# Acknowledgements

- David Lippert, IDOT (retired)
- Steve Robinson, IDOT District 5
- Tom Zehr, Central Bureau of Materials
- Marshall Thompson, Univ. of Illinois

# Questions?

Charles Wienrank

(217) 782-0570

[Charles.Wienrank@illinois.gov](mailto:Charles.Wienrank@illinois.gov)